

DR. DAVID DUMON
SUPERINTENDENT
10105 SOUTH SASABE ROAD
TUCSON, ARIZONA 85736



PHONE: (520) 822-1484
FAX: (520) 822-1798
WWW.ALTARVALLEYSCHOOLS.ORG

January 15, 2016

To Whom It May Concern,

In accordance with the Asbestos Hazard Emergency Response Act (AHERA), accredited building inspectors have completed an asbestos inspection of the Altar Valley Middle School campus, located at 16350 West Ajo Way in Tucson, Arizona. The inspection, performed on September 14 through 16, 2015, was conducted in accordance with the Environmental Protection Agency's (EPA) Rule "Asbestos-Containing Materials in Schools", 40 CFR Part 763.

Samples of suspect asbestos-containing materials were collected during the inspection and were submitted to a laboratory for analysis.

A copy of the inspection reports for each building on the Altar Valley Middle School campus, as well as the periodic surveillance records and the site's Management Plan are kept at the District LEA's office. An additional copy of the previously referenced documents are available during normal business hours from 8:00 a.m. to 3:30 p.m. in the Administrative Office of Altar Valley Middle School.

Sincerely,

A handwritten signature in blue ink, consisting of several loops and a long horizontal stroke extending to the right.

Dr. David Dumon, Superintendent

Altar Valley School District

DR. DAVID DUMON
SUPERINTENDENT
10105 SOUTH SASABE ROAD
TUCSON, ARIZONA 85736



PHONE: (520) 822-1484
FAX: (520) 822-1798
WWW.ALTARVALLEYSCHOOLS.ORG

January 15, 2016

To Whom It May Concern,

In accordance with the Asbestos Hazard Emergency Response Act (AHERA), accredited building inspectors have completed an asbestos inspection of the Robles Elementary School campus, located at 9875 South Sasabe Road in Tucson, Arizona. The inspection, performed on September 22, 2015, was conducted in accordance with the Environmental Protection Agency's (EPA) Rule "Asbestos-Containing Materials in Schools", 40 CFR Part 763.

Samples of suspect asbestos-containing materials were collected during the inspection and were submitted to a laboratory for analysis.

A copy of the inspection reports for each building on the Robles Elementary School campus, as well as the periodic surveillance records and the site's Management Plan are kept at the District LEA's office. An additional copy of the previously referenced documents are available during normal business hours from 8:00 a.m. to 3:30 p.m. in the Administrative Office of Robles Elementary School.

Sincerely,

A handwritten signature in blue ink, appearing to be "David Dumon", with a long horizontal line extending to the right.

Dr. David Dumon, Superintendent

Altar Valley School District